

Technical Information Letter

TIL – 2012-01–20 Nr.: 376

ITS Flame Scanner for use as Replacement Part

This declares that the following designated product

Flame Scanner

Model No.: ITS 967X7179M379

(Product identification)

Replaces following original parts in the full range of functions:

GE Part Number	Honeywell Part Nr.	Description
261A1812P003		Replaced by 261A1812P013
261A1812P004		Replaced by 261A1812P013
261A1812P005		Replaced by 261A1812P013
261A1812P006		Replaced by 261A1812P013
261A1812P007		Replaced by 261A1812P013
261A1812P008		Replaced by 261A1812P013
261A1812P009	LG1093AA05	Replaced by 261A1812P013
261A1812P010	LG1093AA04	Replaced by 261A1812P012
261A1812P011	LG1093AA06	Replaced by 261A1812P013
261A1812P012	LG1093AA24	Flame scanner 16 ft (4,9m) cable
	LG1093AA25	Flame scanner 42 ft (12,8m) cable
261A1812P013	LG1093AA26	Flame scanner 61 ft (18,6m) cable
	LG1093AA34	Flame scanner 16 ft (4,9m) cable
	LG1093AA35	Flame scanner 42 ft (12,8m) cable
261A1812P014	LG1093AA36	Flame scanner 61 ft (18,6m) cable
	LG1093AA44	Flame scanner 16 ft (4,9m) cable
	LG1093AA45	Flame scanner 42 ft (12,8m) cable
261A1812P015	LG1093AA46	Flame scanner 61 ft (18,6m) cable

ITS Industrial Turbine Services GmbH

Fabrikplatz 1, 4662 Steyrermühl

AUSTRIA

(Name / Address)

For the Manufacturer

Date of issue: 2012-01-20



Mark Neeb (CTO)



ITS Industrial Turbine Services
ITS-Industrial Turbine Services GmbH
 Fabrikplatz 1, A - 4662 Steyrermühl
 Tel.: ++43 / (0) 7613 / 44974 - 0
 Fax: ++43 / (0) 7613 / 44974 - 20

