ITS - Flame Scanner

Designation Comparison Chart

Valid from 2020.02.19



ITS 967X7179M372 Flame Scanner - 4.9m (16Ft +/-1Ft) cable length

Honeywell Part No.:

GE Part No.:

LG1093AA01 - Replaced by LG1093AA24
LG1093AA02 - Replaced by LG1093AA24
LG1093AA03 - Replaced by LG1093AA24
LG1093AA03 - Replaced by LG1093AA24
LG1093AA04 - Replaced by LG1093AA24
LG1093AA04 - Replaced by LG1093AA24
LG1093AA04 - 4.9m (16Ft +/-1Ft) cable length
LG1093AA34 - 4.9m (16Ft +/-1Ft) cable length
LG1093AA44 - 4.9m (16Ft +/-1Ft) cable length



ITS 967X7179M379 Flame Scanner - 18.6m (61Ft +/-1Ft) cable length

GE Part No.:

261A1812P003 - Replaced by 261A1812P013
261A1812P004 - Replaced by 261A1812P013
261A1812P005 - Replaced by 261A1812P013
261A1812P006 - Replaced by 261A1812P013
261A1812P007 - Replaced by 261A1812P013
261A1812P008 - Replaced by 261A1812P013
261A1812P009 - Replaced by 261A1812P013
261A1812P011 - Replaced by 261A1812P013
261A1812P013 - 18.6m (61Ft +/-1Ft) cable length
--261A1812P014 - 18.6m (61Ft +/-1Ft) cable length
--261A1812P015 - 18.6m (61Ft +/-1Ft) cable length

TSL Part No.:

Nuovo Pignone No.:

TSL 261A1812P013

PRO 56028

Honeywell Part No.:

LG1093AA05 - Replaced by LG1093AA26
LG1093AA06 - Replaced by LG1093AA26
LG1093AA25 - 12.8m (42Ft +/-1Ft) cable length
LG1093AA35 - 12.8m (42Ft +/-1Ft) cable length
LG1093AA36 - 18.6m (61Ft +/-1Ft) cable length
LG1093AA36 - 18.6m (61Ft +/-1Ft) cable length
LG1093AA45 - 12.8m (42Ft +/-1Ft) cable length
LG1093AA46 - 18.6m (61Ft +/-1Ft) cable length

Powmat Part No.:

BFA 2181 - 13



Doc.ID.: TS106 Editor: MM



ITS 184X0254M029 Flame Scanner - C € € II 3G EEx nA IIC T3/T2 Gc

GE Part No.: Reuter-Stokes Part No.: Ametek Part No.:

362A1052P001 RS-FS-9001 Spectra GT30

362A1052P003

362A1052P004

362A1052P103 Powmat Part No.: Nuovo Pignone Part No.:

362A1052P104

362A1052P203 362A1052P204 362A1052P303 362A1052P304 362A1052P404 121T9685P0001



ITS 184X0254M123 Flame Scanner - C € 🖾 II 1G EEx ia IIC T3/T2 Ga

GE Part No.: Reuter-Stokes Part No.:

362A1052P106 RS-FS-9004

362A1052P107 362A1052P306 362A1052P307 121T9685P0010



Doc.ID.: TS106 Editor: MM