

Technical Information Letter

TIL Nr.: 379 – 2013-03-07
ITS Flame Scanner for use as Replacement Part

This declares that the following designated product

Flame Scanner
Model No.: ITS 967X7179M372

(Product identification)

replaces the following original parts in the full range of functions:

GE Part No.

261A1812P010 - Replaced by 261A1812P012
261A1812P012 - 16 ft (4,9m) cable length

Honeywell Part No.

LG1093AA01 - Replaced by LG1093AA24
LG1093AA02 - Replaced by LG1093AA24
LG1093AA03 - Replaced by LG1093AA24
LG1093AA04 - Replaced by LG1093AA24
LG1093AA24 - 16 ft (4,9m) cable length
LG1093AA34 - 16 ft (4,9m) cable length
LG1093AA44 - 16 ft (4,9m) cable length

ITS Industrial Turbine Services GmbH
Fabriksplatz 1, 4662 Steyrermühl
AUSTRIA

(Name / Address)

For the Manufacturer

Date of issue: 2016-05-04



Mark Neeb (CTO)

Under penalties of perjury, we declare that we have examined this certification statement, and to the best of our knowledge and belief, the facts presented are true, correct and complete.

